


Bona Universal AMO110000.0 Universal Motor 1-3 ph



Bona Universal AMO110000.0 Universal Motor 1-3 ph

.	ASO115820	Motor, cap.box 1-3 ph compl.
.	ASO115920	Cap.box 1-3 phase compl
045 .	ASO115045	Motor pulley
047 .	ASO115147	Cap.box cover
048 .	ASO115148.3	Base plate grey
050 .	ASO900130	El.motor 3 KW 220/380V ABM
051 .	ASO115051	Hinge for motor
052 .	ASO115152	Tensioner screw
063 .	ASO115163	Intermediate plate
064 .	ASO115164	Front motor bracket
069 .	ASO115169	Mounting plate
083 .	ASO945132	Lifting handle motor
104 .	ASO922250	V-belt ventilator Z-25 ABM
106 .	ASO951518	Screw M6S M8x20 fzb
107 .	ASO965001	Washer 8,5 X 30 X 4 fzb
116 .	ASO920310	V-belt A31
130 .	ASO960900	Nut M6M M16 fzb
132 .	ASO952515	Screw MC6S M8x14 fzb
133 .	ASO952420	Screw MC6S M6x30 fzb
135 .	ASO965003	Washer 8,2 X 26 X 5 fzb
136 .	ASO951519	Screw M6S M8x25 fzb
137 .	ASO952416	Screw MC6S M6x16 fzb
138 .	ASO903416	Motor inlet 1-3 phase

139 .	ASO903752	Switch compl.with the lamp
142 .	ASO115172	Rubber sealing motor base plat
143 .	ASO952416	Screw MC6S M6x16 fzb
144 .	ASO968002	Spacer DB 6x12,5x0,2
145 .	ASO958121	Screw MRX M5x35 fzb Philips
149 .	ASO932820	Key 8x7x20
150 .	ASO903750	Contactore 5,5 kW 100-M12N
151 .	ASO903754	Transformer
153 .	ASO903755	Circuit card univ. 1-1/3 phase
154 .	ASO903102	Start condensator 100 uF
155 .	ASO903140	Condensator cont.use 140 uF
156 .	ASO115256	Mounting plate for capacitor b
157 .	ASO906032	Plinth